

The background of the slide features a lighthouse with a black and white spiral pattern on its tower, set against a dark, moody sky. The lighthouse is positioned on the left side of the frame. The overall color palette is dominated by dark blues and greys, with a bright blue diagonal shape cutting across the middle of the slide.

Industry software maintenance standard

Aron Sørensen – Head of Maritime technology and regulation, BIMCO
On behalf of BIMCO and CIRM

e-Navigation Underway 2018

A dark blue background with a grid pattern and various glowing blue and white lines, some with arrows pointing left, creating a technical or digital aesthetic.

What are the challenges?

Software maintenance – example 2013

After black out due to repair cooling water valve 19/2, we have got a problem with (*name of main engine*).

It keeps coming up with failure:

Failure no 3633 (Cant Load DLL: MSJTER35.DLL Module frm Card Failure

Procedure: add failure

Line 50750

Choices are to press continue or exit program.

If pressing continue the error comes back after some seconds/minutes.

We have tried to restart a couple of times and same error comes back.

Now the pc is blocked and we can not operate from pc in ECR.

But the engine is running ok.

Engine Speed [????]
 er (FuelCmd x r) [????]
 r mean pressure [????]
 Master [????]
 Engine State [????]

Fuel Rail

Setpoint [????]
 Mean value [????]
 Actuator output [????]

Injection

Injection begin [????]
 VIT + FQS (IT_G) [????]
 Inj. with [????]

Control Oil Rail

vr. Orders

Control [????]
 [????]
 [????] [????]
 [????]

Commands RC / Backup

Fuel Cmd [????]

V-Config Vers.:031-1 10.03.

DESIGNATION

CYL-EU#2 is SSI-Bus Clock M

CYL-EU#1 is SSI-Bus Clock M

COM-EU#1 is MASTER

Cyl. 8 failure (slowdown)

Cyl. 7 failure (slowdown)

Cyl. 5 failure (slowdown)

Cyl. 4 failure (slowdown)

Cyl. 3 failure (slowdown)

Cyl. 2 failure (slowdown)

Cyl. 1 failure (slowdown)

Leakages

Servo oil supply unit, Leak [????]
 Ctrl. Oil Supply Unit, Leak [????]
 Fuel supply unit, Leak [????]
 Rail unit, General Leak. fore/aft [????] [????]
 ICU & Fuel Pipe Leak. fore/aft [????] [????]
 CtrlOilPipeLeakPressure [????]

Journal | Gr

flexView V4.0.3 - Fehlermeldung

A flexView programm error occured. Try to continue or exit programm.

Failure-Desc

Failure-No:

Module:

Procedure:

Line-No:

Failure-Prot

Further Program Execution ...

Continue Exit program

flexView Initialise

memorising variables ...

Initialise zip ...

Startup-Mode: STANDARD

Initialise cards ...

Initialise can interface ...

Autodetection of PPCan ...

PPCan-Driver is not installed!

Autodetection of USB-Can ...

USB-Can is ready!

Hide events

LOG TIME	RESTORING TIME
19 05:24:48.435	23/11/2009 10:59:34.225
19 05:22:59 ----	23/11/2009 05:24:48.335
19 05:22:58 ----	
19 05:19:34 ----	23/11/2009 05:23:22 ----
19 05:19:33 ----	23/11/2009 05:23:12 ----
23/11/2009 05:19:33 ----	23/11/2009 05:23:10 ----
23/11/2009 05:19:33 ----	23/11/2009 05:23:08 ----
23/11/2009 05:19:32 ----	23/11/2009 05:23:05 ----
23/11/2009 05:19:32 ----	23/11/2009 05:23:05 ----
23/11/2009 05:19:32 ----	23/11/2009 05:23:03 ----

Software system after a black out

- Better software quality that are tested to ensure that such things does not happen
 - We need to prevent and avoid that a maintenance event creates problems due to integration of software

Another example

- Antenna problem – a service provider from another company than the original manufacturer comes on board
- The technician has problems, he cannot update the existing software, so he decides to install a new version of the software
- The problem is that the original manufacturer does not support the version that is being installed

power steady green
terminal teady red
antenna steady red

CONDITION FOUND + ACTIONS TAKEN

On arrival try to connect to BDU with the TMA tool without success, did factory reset and now is possible to access the BDU also LEDs were back to normal. SW ver. founded 1.19 tried to do sw update without success. Still no communication. Connect a new BDU same result. Proceed to replace the ATM and now system is back to normal, performed a software update now SW ver. 1.21. Master test the system.

Equipment is back to normal, in good working order.

Replaced the Antenna Tracking Module.

EQUIPMENT SERIAL NO.	10449100	HARDWARE VERSION	FBB 500	SOFTWARE VERSION	1.19	[Found]	SOFTWARE VERSION	1.21	[Updated]
----------------------	----------	------------------	---------	------------------	------	---------	------------------	------	-----------

FINAL CONDITION OF EQUIPMENT	System is back to normal	FOLLOW UP NEEDED ?	NO
------------------------------	--------------------------	--------------------	----

SPARE PARTS / MATERIALS / SERVICE CODES

QTY	PART DESCRIPTION	PART NUMBER	S/N NEW PART	S/N DEFECTIVE PART	T.B.RAn?
1	ANTENNA TRACKING MODULE	THS-62- 128256AT	P5800033050112	22002125025	YES



The following day

- Good day,
- Please find service report attached - FBB has been checked and found OK.

Good day Captain,

Noted your below email with thanks.

Please note,
Software has been upgraded to a version not accepted by XX.
We believe instruction for downgrade might be available on board which was forwarded by XX During EVC migration.
Can you please check if staff on board can do the downgrade to version 1.19?
Only version accepted by XX is 1.19

Challenges continued

Nobody told the technician to replace software version. This is not aligned with the policies of the manufacturer

The software in the antenna tracking module (ATM) led to failure of other software, making it impossible to connect / communicate at service level

Need for better co-operation between service provider, master, owner and manufacturer

There is a need to be able to return to the previous software version so the ship can operate safely if the maintenance goes wrong

What is the solution?

Were a

- Ship's s
automat
- e-Navig
- Many “
ware re

**Calls for a standard on
software maintenance**

d



egration, and
t on board
digm shift
her than hard



Success

- BIMCO approached CIRM in 2013
- CIRM/BIMCO Joint Working Group (JWG) established 2014
- A pilot project tested the draft standard in 2017


- Version 1.0 published January 2018

**Industry Standard on
Software Maintenance of Shipboard Equipment**

Version 1.0

Produced by the CIRM/BIMCO Joint Working Group

Many stakeholders in different roles



Increasing awareness/visibility of situation on board



Electronic Service Report

- Completed by service role at the conclusion of SW maintenance
- Standard specifies minimum content

Onboard software log

- Shipboard repository of electronic service reports
- Implemented and maintained by shipowner role

Availability of software updates

- Producer role provides information about available SW and updates

Awareness of software versions

- Equipment must display on demand the current SW version

Ensuring effective planning of SW maintenance



Checklist for communicating a software problem

- Communicated by the shipowner role to other roles

Producer role

- If update to be performed by crew, provide detailed instructions

Service role

- Plan and describe work expected to be undertaken
- Agree time, place and maintenance requirements with shipowner

Shipowner role

- Prepare plan in advance of SW maintenance

System integrator role

- New updates must be assessed to determine impacts on software installed on connected equipment

Ensuring competencies of service personnel

Software maintenance competency requirements

- required competencies for different levels of SW maintenance

Producer role

- Must specify maintenance requirements in maintenance manuals

Service role

- Must have auditable QA system covering competence management
- Must meet producer's maintenance requirements
- Train-the-trainer model as a minimum; for certain types of equipment technicians may require additional testing/certification by the producer

Improving cyber security

Producer role

- Equipment must provide protection against unauthorized access (e.g. IEC 60945)



Service role

- Maintenance operations must not lead to malware infection
- Requirements on use of removable storage devices and malware checks
- Restrictions on connection to “controlled networks”

Shipowner role

- Procedures must be in place to protect equipment against malicious or unintentional security threats

SW maintenance a controlled process



Improving production of software

- Support procedures for on-the-spot diagnostic report after maintenance Software
- Role-back to previous safe state in case of errors during update
- Means to check that interfaces and functionality are operating as expected

What is next?

- All stakeholders are encouraged to implement and use the standard:
 - manufacturers; software houses; IT subcontractors; data suppliers; service providers; servicing companies; technicians; shipowners; masters and crews
- Possibly to be added to BIMCO ship repair standard contracts
- Evolve into an ISO standard



The background of the slide features a tall, spiral-patterned lighthouse on the left side, illuminated from within. The scene is set against a dark, cloudy sky. A large, semi-transparent blue shape, resembling a stylized wave or a large letter 'B', is overlaid on the right side of the image, serving as a backdrop for the text.

Thank you!

Contact BIMCO at
www.bimco.org

and CIRM at [www.CIRM .org](http://www.CIRM.org)